

# REPORT of SURVEY for REPAIRS.

No. 187 Survey held at London Date May 31 1839  
on the Bg Viscount Downe Master W. West  
Tonnage 230 Built at Thames When built 1825  
By whom built \_\_\_\_\_ Owners Parson  
Port belonging to Hull Destined Voyage St Petersburg  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ Classed A, 1 with the British  
Port London 5.2799. Leith 365, London 4229, 4922.

**Repairs** At the present time new 9 inch water added to the Stentions  
two pair of Iron Diagonal Braces to the hold beams  
one new lodging brace and one new plank in the Deck

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails	Cables
Hatchway Comings	(Outside to the Water's Edge)	Anchors No. of
Breasthooks	Rudder	Standing & Running Rigging
	<u>Cover</u>	

General Observations and Opinion, In very good condition & I am of opinion she will  
as required by the Instructions, retain her present class

W. West

The Amount of Fee.....£ : : is received by me,

Committee Minute 4 June 1839

Character assigned A, 1