

# REPORT of SURVEY for REPAIRS.

*[Handwritten signature]*

No. <sup>31</sup> Survey held at London Date May 2 1839  
 on the Ship Warrior Master Brown Wm Cooney  
 Tonnage 301 Built at Dundee When built 1837  
 By whom built \_\_\_\_\_ Owners Blain  
 Port belonging to Gundles Destined Voyage C. L. Hope  
 If Surveyed Afloat or in Dry Dock Ship<sup>r</sup> Kitchens Dock

Original Survey, No. 273 Dated 1837 Classed 7 A 1  
 Port Dundee

**Repairs** *at the present time stopped, caulked from the knee up & coppered to the water*

*New Masts  
16 Iron Knees*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions, *In my opinion this ship is entitled to remain as at present classed 7 A 1*

*[Handwritten signature: George Bayley]*

The Amount of Fee.....£ 1 : 1 : - is received by me, *[Signature]*

Committee Minute 16 July 1839

Character assigned 7 A 1 Record Copper *[Signature]*

