

REPORT of SURVEY for REPAIRS.

5-465

No. ²⁰⁴ Survey held at London Date July 12 1839
 on the Bark Black River Packet Master Bright
 Tonnage 265 Built at Southampton When built 1825
 By whom built _____ Owners W^m Morris
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Blackwall Dry Dock

Original Survey, No. 864, 1880 Dated 1839 Classed *F. 1
 Port London 3861

Repairs At the present time stripped, caulked from the keel up and
recooped on 12 to 14 feet buches

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion this ship is entitled to remain
as at present classed *F. 1

George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, HA

Committee's Minute 26 July 1839

Character assigned F. 1 Antient - good ship