

REPORT of SURVEY for REPAIRS.

No. ³⁶⁷ Survey held at London Date April 15th 1839
on the Bk Gratitude Master W. R. Weston
Tonnage 271 Built at Yarmouth When built 1833
By whom built Fellows Owners Sedgell & Co
Port belonging to London Destined Voyage West Town
If Surveyed Afloat or in Dry Dock in New Crane Dock

Original Survey, No. 12M. 4513 Dated _____ Classed 11 A 1
Port London

Repairs Copper stripped off caulked from the keel to the gunwale
and sheathed with Yellow Metal, the upper course
of the bottom over Galt & lower part over planks

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion Is in a very high state of efficiency and may
as required by the Instructions, continue as Classed
W. R. Weston

The Amount of Fee.....£ 1 : 1 : - is received by me,

Committee Minute 26 July 1839

Character assigned 11 A 1 W. R. Weston