

5467

REPORT of SURVEY for REPAIRS.

No. 168 Survey held at W. W. W. Date 23rd July 18 39
on the Sh^{ip} Isabella Master W. W. W.
Tonnage 109 Built at Peterhead When built 1830
By whom built — Owners Nicholson
Port belonging to Peterhead Destined Voyage —
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 202 Dated — Classed F. 1
Port Dundee & 3167 London

Repairs

At Malta recently, all new masts, rigging
Sails —

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>good</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Sails <u>different</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

Is in good and efficient condition
fit for the conveyance of any and perishable cargo
and may be continued as before

The Amount of Fee.....£ : : is received by me,

Committee's Minute 26 July 18 39

Character assigned F. 1