

REPORT of SURVEY for REPAIRS.

& Change of Owners

No. 29 Survey held at London Date July 26th 1839

on the Bk. Arista Master J. Ryde

Tonnage 294 Built at Shields When built 1834

By whom built _____ Owners London & Newcastle Shipping Company

Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock Afloat in the London Dock

Original Survey, No. 710 Dated 1837 Classed 10 A 1

Port of London Liverpool & London 32 1/4

Repairs Bottom stripped, caulked & sheathed with Yellow Metal over Felt

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>&</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables <u>Efficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinion, In a very efficient state & eligible to
as required by the Instructions, retain her present Plaps

W. Woodson

The Amount of Fee.....£ 1 : 1 : - is received by me, HS

Committee's Minute blank 1839

Character assigned 10 A 1 second Reading