

ANNUAL SURVEYS.

5547

No. 673 Survey held at London Date Aug 13 1839
 on the Ship Mermaid Master Chapman
 Tonnage 473 Built at Calcutta When built 1817
 By whom built _____ Owners Chapman
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Smithkin Dock

Original Survey, No. 1583.3093 Port of London May 1838 Classed *A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good and efficient*

General Observations and Opinion, *At the present time Yellow sheet largely repaired as required by the Instructions, having been washed off - She is in my opinion in a good and efficient state for remaining as classed *A1*

Committee Minute 20 Aug 1839 *George Bayley*
 Character assigned A1 *1000*

No. 340 Survey held at London Date August 17 1839
 on the Bank Wilmore Master Miller
 Tonnage 687 Built at St. George When built 1836 Sto
 By whom built _____ Owners Shaper
 Port belonging to Glasgow Destined Voyage Hobart Town Sydney
 If Surveyed Afloat or in Dry Dock St. George Dock

Original Survey, No. 1606 Liverpool Port of London July 1839 Classed 4A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Good & efficient*

General Observations and Opinion, *Since the date of the Report in July - Has had a new main price of Rudder. So as to steer on the poop. and two Iron knees substituted for wood Transom knees. over the foremast - She is in good & efficient state*

Committee Minute 20 Aug 1839 *George Bayley*
 Character assigned 4A1 *1000*

17th August

1st Repair

2 Annual

8



© 2019

Lloyd's Register
Foundation