

# REPORT of SURVEY for REPAIRS.

*[Handwritten signature]*

No. 267 Survey held at London Date 21<sup>st</sup> Aug 18 39.  
on the Ship Marion Master Pope.  
Tonnage 684 Built at Calcutta. When built 1834  
By whom built \_\_\_\_\_ Owners Pope & Co.  
Port belonging to London. Destined Voyage Calcutta.  
If Surveyed Afloat or in Dry Dock Blackwall Dock.

Original Survey, No. 3542 Dated 1837 Classed 12 A. 1.  
Port London.

**Repairs** *at Present time - In consequence of having been on shore. Shipped - Caulked from keel up. Felled - Sheathed with 1 1/2 inch deal and Yellow metal to the wale. -*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting <i>Good</i>	Wales <i>Good</i>	Masts, Yards, &c. <i>Good &amp; efficient</i>
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
as required by the Instructions,

*In my opinion this ship is fully eligible  
to remain as at present Classed 12 A 1  
George Bayley*

The Amount of Fee.....£ 3 : 3 : - is received by me, *[Signature]*

Committee's Minute 27 Aug 1839

Character assigned 12 A 1 minor repairs

*Special Damages £5.5*

2000-90907