

REPORT of SURVEY for REPAIRS.  
& Change of Owners

No. 94 Survey held at London Date April 19 1839  
on the By Defence Master W. Dittis  
Tonnage 142 Built at Shields When built 1827  
By whom built \_\_\_\_\_ Owners J. Kitten  
Port belonging to Yarmouth Destined Voyage Baltic  
If Surveyed Afloat or in Dry Dock on the Mays

Original Survey, No. 1034450 Dated \_\_\_\_\_ Classed A. 1  
Port London

Repairs Bottom examined

Surveyor is also required to state the present Condition of the

Deck Beams & Fastenings	Transoms	Windlass
Deck Beams & Fastenings	Timbers of the Frame	Capstan
Deck Beams & Fastenings	Topsides	Pumps
Deck Beams & Fastenings	Wales	Masts, Yards, &c.
Deck Beams & Fastenings	Counter	Sails
Deck Beams & Fastenings	Plank & Treenails (Outside to the Water's Edge)	Cables
Deck Beams & Fastenings	Rudder	Anchors No. of
Deck Beams & Fastenings	Copper	Standing & Running Rigging

al Observations and Opinion, Is in a very efficient state for the safe  
required by the Instructions, conveyance of dry & perishable cargoes  
and may retain his present class

W. Dittis

The Amount of Fee.....£ \_\_\_\_\_ is received by me,

Committee Minute 20 Sept 1839

Character assigned B. A.

