

REPORT of SURVEY for REPAIRS.

5645

Handwritten signature/initials

No. 201 Survey held at London Date Jan 7/14-25 1839
 on the Steamship Grand Turk Master June
 Tonnage 243 Built at Greenock When built 1837 June
 By whom built _____ Owners Commercial Steam Co
 Port belonging to London Destined Voyage Boulogne
 If Surveyed Afloat or in Dry Dock Blackett's Dock, Afloat

Original Survey, No. 3693* Dated 1837 Classed 5A1
 Port London, Clyde 1443

Repairs *at the present time stopped - Bottom additionally fastened, Caulked throughout and generally overhauled - Machinery examined and made good -*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *at the present time my opinion that this vessel is eligible to remain as classed 5A1*
 as required by the Instructions,

24 Feb

George Bayley

The Amount of Fee.....£..... is received by me,

Committee Minute 20 Dec 1839

Character assigned 5 A 1