

# ANNUAL SURVEYS.

5747

No. 209 Survey held at London Date October 19 1839  
 on the Bk Eliza Master R. Derrin  
 Tonnage 393 Built at Java When built 1815  
 By whom built \_\_\_\_\_ Owners T. Ward  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 209,389 Port of London 1839 Classed A. 1

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirkettling                  | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, At the present time four of the old beams scaphs  
 as required by the Instructions, which were broken, partially caulked, and some  
of the beam fastenings were out for examination & found very good, and  
the is altogether in a very efficient state no symptoms of weakness or decay  
and I am of opinion is fit for the safe conveyance of dry & perishable cargoes  
to & from all parts of the world and may be raised to A. 1 with the British  
 Committee Minute 22 Dec 1839

Character assigned

A. 1

Asterisk

Wm. W. W. W.  
24 Dec 1839  
Not examined. g. L. D. W.

No. 473 Survey held at London Date October 16 1839  
 on the Bg Andrew Melburn Master G. W. W.  
 Tonnage 221 Built at Leith When built 1825  
 By whom built \_\_\_\_\_ Owners G. W. W.  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 557,254 Port of London 1839 Classed A. 1  
3877,4700

The Surveyor is required to state the present Condition of the

|                               |   |                            |
|-------------------------------|---|----------------------------|
| Decks                         | Breasthooks   | Capstan                    |
| Upper Deck Beams & Fastenings | Transoms  | Pumps                      |
| Lower Deck Beams & Fastenings | Timbers of the Frame                                  | Masts, Yards, &c.          |
| Spirkettling                  | Topsides  | Sails                      |
| Plank Shears                  | Wales   | Cables                     |
| Waterways                     | Plank and Treenails<br>(Outside to the Water's Edge.) | Anchors No. of             |
| Hatchway Comings              | Rudder  | Standing & Running Rigging |
|                               | Windlass  | Copper                     |

General Observations and Opinion, New Carick Bitts & Hatchway Comings, is altogether  
 as required by the Instructions, in a very good state of efficiency both in the Hull  
& Stowage and may continue her present class

Committee Minute

22 Dec 1839

Character assigned

A. 1

W. W. W.



© 2019

Lloyd's Register  
Foundation

8020-9098-0208