

ANNUAL SURVEYS.

5750

No. ⁶³⁶ Survey held at London Date 18 Oct 1839
 on the Sch Anne Master Burgess
 Tonnage 164 Built at Swanland When built 1819
 By whom built Taylor Owners Taylor
 Port belonging to London Destined Voyage Loango
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 1975, 2815, Port of London Classed 17/1
3008, 4197

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>good</u>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>good</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Continues in good and efficient condition and may be continued as before

Committee Minute 22 Oct 1839

Character assigned 17/1

No. ³⁷⁵ Survey held at London Date 11 Oct 1839
 on the Sullock Castle Master Briggs
 Tonnage 503 Built at London When built 1827
 By whom built - Owners Capitson
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock afloat

Original Survey, No. 639, 1923, Port of London Classed 12 A/1
2646, 3535, 4547

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Shears	Wales	Cables <u>good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>good</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Is in good and efficient condition and may be continued as before

Committee Minute 22 Oct 1839

Character assigned 12 A/1