

No. 5633 Survey held at London Date Sept 26 18 39 5760
 on the Brig William Tulcher Master Hy Lawes
 Tonnage _____ Built at Richmond When built 1839
 By whom built J Crook Owners Brichley
 Port belonging to London Destined Voyage Nevis
 If Surveyed Afloat or in Dry Dock Not in Dry Dock

Original Survey, No. 5633 Port of London Classed 10 A
18 Oct 1839

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Red Pine good</u> x
Spirketting	Topsides	Sails <u>2 built ready</u> x
Plank Shears	Wales	Cables <u>2C 180 fms 1 1/2 in 1/4 in 1/8 in</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>2B 18 1H</u> x
Hatchway Comings	Rudder	Standing & Running Rigging <u>New Sufficient</u>
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions,

Coppered to 12 feet abaft — The stow not yet
completed 2 1/2 B A See above
George Bayley

Committee Minute 26 Oct 1839

Character assigned

10 A second class