

ANNUAL SURVEYS.

5845

No. 218 Survey held at London Date 22 Nov^r 1839
 on the Ship Forester Master M^r Arthur
 Tonnage 370 Built at Chesham When built 1826
 By whom built - Owners Ellice Ho
 Port belonging to London Destined Voyage Tobago
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3800, 4660 Port of London 5573 Classed A1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling <u>good</u> | Topsides | Sails <u>Sufficient</u> |
| Plank Shears | Wales <u>good</u> | Cables <u>all good</u> |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion,
 as required by the Instructions,

Is in good and efficient condition fit for the
conveyance of dry and perishable cargo and may be continued
as classed

Committee Minute 26 Nov 1839

Character assigned

A1 as usual

No. 117 Survey held at London Date 22 Nov^r 1839
 on the Pegasus Master Cook
 Tonnage 223 Built at Sheeps When built 1827
 By whom built - Owners Blackburn
 Port belonging to London Destined Voyage Torshavn
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2230, 4687 Port of London Classed A1

The Surveyor is required to state the present Condition of the

| | | |
|--------------------------------------|---|----------------------------|
| Decks <u>plank all but very good</u> | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides <u>good</u> | Sails <u>Sufficient</u> |
| Plank Shears <u>good</u> | Wales | Cables <u>all</u> |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of <u>good</u> |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

General Observations and Opinion,
 as required by the Instructions,

The decks are becoming worn in places but
are light at the present in other respects she is in good
and efficient condition and may be continued as classed

Committee Minute 26 Nov 1839

Character assigned

A1



© 2019

Lloyd's Register
 Foundation