

Coppering 5903

REPORT of SURVEY for REPAIRS.

No. 117 Survey held at London Date Dec 7 1839
 on the Shoona Isabel Master Kerr
 Tonnage 123 Built at Eastney When built 1831
 By whom built Ransom Shipley Owners J & S Adam
 Port belonging to London Destined Voyage St Michaels
 If Surveyed Afloat or in Dry Dock Hackwood Dock

Original Survey, No. 250,3098, Dated Jan 3 1839 Classed 12 A 1
 Port London
4880,

Repairs *at the present time stripped carried from the keel up and generally overhauled sheathed with Yellow Metal on top to 11.0*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions, *In my opinion the vessel is fit to remain as classed 12 A 1*

George Bayley

The Amount of Fee.....£ 10 : 6 is received by me,

Committee's Minute 20 Dec 1839

Character assigned 12 A 1 *renewed sheathed*



1830-909207