

Change of Property **REPORT of SURVEY for REPAIRS.**

6046
[Signature]

No. 180 Survey held at London Date February 2. 1840
 on the Shannon Flora Master Raney
 Tonnage 151 Built at Bridport When built 1826
 By whom built _____ Owners London Waterland & Shipb's Exports
 Port belonging to London Destined Voyage Waterford
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 1 Dated 1838 Classed 10 F. 1 expunged
 Port Waterford

Repairs *Carried in 1839 and is at the present time in a very efficient state for the safe conveyance of dry & perishable cargoes to & from all parts of the world.*

[Signature]

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

[Handwritten notes: "Good" in several boxes, "Good & efficient" for Masts, Yards, &c., and Sails]

General Observations and Opinion,
 as required by the Instructions,

In my opinion this vessel is eligible for the conveyance of dry and perishable cargoes to and from all parts of the world & should be classed F. 1

[Signature: George Bayley]

The Amount of Fee.....£ — : 10 : 6 is received by me, *[Signature]*

Committee's Minute 14th Feb 1840

Character assigned F. 1

[Signature: Mr Taylor Secy. Geo. Thorne]

