

REPORT of SURVEY for REPAIRS.

Change of property 6127
 [Signature]

No. 341 Survey held at London Date 28 Feb 1840
 on the "Britannia" Master J. W. Mear
 Tonnage 186 Built at Farmouth When built 1827
 By whom built _____ Owners R. W. Hyde
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 132 Dated _____ Classed 10 Δ \ Cont. 1837 3 J. J.
 Port London, Lic. 2266,

Repairs

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Sufficient</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Sails <u>good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

I am good & sufficient condition for
the voyage of any and possible cargo may
be continued as classed
 [Signature]

The Amount of Fee.....£ 1 : 1 : — is received by me, [Signature]

Committee's Minute 10th March 1840

Character assigned Class 3 A