

# ANNUAL SURVEYS.

6136

No. 85 Survey held at London Date Sept 24 1840  
 on the By Patriot Master J Webster  
 Tonnage 261 Built at Montrose When built 1833  
 By whom built \_\_\_\_\_ Owners Davidson  
 Port belonging to Dundee Destined Voyage Constantinople  
 If Surveyed Afloat or in Dry Dock in the St. Katherine's Dock

Original Survey, No. \_\_\_\_\_ Port of 1839 Dundee Classed 7A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Good</u>	Capstan
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>and wharves</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>Good</u>	Topsides	Sails <u>Well found</u>
Plank Shears	Wales	Cables <u>"</u>
Waterways	Plank and Treenails <u>Good</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder	Standing & Running Rigging <u>Good</u>
	Windlass	

General Observations and Opinion, Survey good condition and may continue as before  
 as required by the Instructions,

Committee Minute \_\_\_\_\_ 183

Character assigned \_\_\_\_\_

No. 268 Survey held at London Date March 7 1840  
 on the Sr Sively Master Morris  
 Tonnage 104 Built at London When built 1824  
 By whom built \_\_\_\_\_ Owners Harbour of London & Rly. Co. & Ass.  
 Port belonging to London Destined Voyage Waterford  
 If Surveyed Afloat or in Dry Dock in your Dock

Original Survey, No. London 566 Port of Shewich, Lon. 4159 1836 Classed Best 1836

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Good</u>	Capstan
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>and wharves</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears	Wales <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	

General Observations and Opinion, Is in a very efficient state and at the present time  
 as required by the Instructions, Bottom caulked, and is in good condition to retain  
her present Character

Committee Minute 10th March 1840

Character assigned Best 6A

