

REPORT of SURVEY for REPAIRS.

No. 162 Survey held at London Date Feb & March 1840
 on the Ship William Master Bustfield
 76 Tonnage 61 Built at Blythe When built 1814
 By whom built _____ Owners Society & Co
 Port belonging to London Destined Voyage Holland
 If Surveyed Afloat or in Dry Dock on the Wagon

Original Survey, No. 1346, 3303 Dated 4003, Classed A, 1
 Port of London

Repairs At the present time now held on, ten stakes of Ceiling
 in each side timbers rechecked, Bilges & Butts retimed
 with Copper, two pair of Iron hanging benches, one new
 Iron Breasthook new Decks, one plank in the Wale
 shifted, caulked from the Keel upwards and general
 examination —

The Surveyor is also required to state the present Condition of the

Decks <u>new</u>	Transoms <u>Grand</u>	Windlass
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Standard</u>	Capstan
Lower Deck Beams & Fastenings	Topsides <u>Good</u>	Pumps
Spirkettling <u>new</u>	Wales <u>Good</u>	Masts, Yards, &c. <u>Well</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Grand</u>
Waterways <u>Good</u>	Plank & Treenails (Outside to the Water's Edge) <u>Good</u>	Cables
Hatchway Comings <u>Good</u>	Rudder <u>Good</u>	Anchors No. of
Breasthooks <u>Good</u>	Keel <u>Good</u>	Standing & Running Rigging

General Observations and Opinion, In very good condition for the safe conveyance of
 as required by the Instructions, dry & stowable cargoes and may continue A, 1

The Amount of Fee.....£ : 10 : 6 is received by me, [Signature]

Committee's Minute 13th March 1840

Character assigned A, 1