

# ANNUAL SURVEYS.

6323

No. 286 Survey held at April 26<sup>th</sup> at London Date 1840  
 on the By Champion Master J Clarke  
 Tonnage 202 Built at Amboise When built 1826  
 By whom built \_\_\_\_\_ Owners Rance  
 Port belonging to London Destined Voyage Lady  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2366, 4401 Port of London 1830 Classed A1  
4716

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Good</u>	Transoms _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Timbers of the Frame <u>Sound &amp; unshaken</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	<del>Cables</del>

General Observations and Opinion, Good condition for the safe conveyance of Dry & perishable cargo and may remain as before  
 as required by the Instructions,

Committee Minute 1<sup>st</sup> May 1840

Character assigned A1

No. 78 Survey held at London Date April 20<sup>th</sup> 1840  
 on the By Unity Master J Brown  
 Tonnage 110 Built at Hull When built 1830  
 By whom built \_\_\_\_\_ Owners Brown & Co  
 Port belonging to London Destined Voyage London  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 4284 Port of London 1830 Classed 10 A1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>Good</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>Sufficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Caution in 1839 from the keel to the gunwale  
 as required by the Instructions, in very good condition throughout and may retain her present character

Committee Minute 1<sup>st</sup> May 1840

Character assigned 10 A1