

REPORT of SURVEY for ^{Change of Owners 6343} ~~REPAIRS~~.

No. _____ Survey held at London Date Dec 1839
 on the ~~SS~~ By Sumatra Master J Harvey
 Tonnage 143 Built at Pirle When built 1834
 By whom built _____ Owners J P Morgan
 Port belonging to London Destined Voyage Havannah
 If Surveyed Afloat or in Dry Dock in the Ways

Liverpool 1437.
 Original Survey, No. 3083, 3094 Dated 1839 49/40. Classed 11A1
 Port of India

Repairs Bottom examined & Copper patched

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in very good condition throughout both in the Hull
 as required by the Instructions, & Masts and may retain her present Class

The Amount of Fee.....£ / : / : — is received by me, AS

Committee's Minute 8th May 1840

Character assigned 11A1

