

REPORT of SURVEY for REPAIRS.

Coppering 6354

No. 418 Survey held at London Date May 5 1840
 on the Barb New Master Gapp
 Tonnage 409 Built at Glasgow When built 1835
 By whom built _____ Owners Battersea
 Port belonging to Liverpool Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Ratcliff Croft Dock

Original Survey, No. 2205, 2702 Dated March 1839 Classed 7A1
 Port Liverpool

Repairs

at the present time in consequence
 of having been ashore shipped, carried
 from keel up - a broken Upper Deck Beam
 shifted and reopposed to 2nd stake of
 bale from below

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

My opinion the vessel is eligible
 to remain as classed 7A1

George Bayley

The Amount of Fee.....£ 1 : 1 : — is received by me, HA

Committee's Minute 12th May 1840

Character assigned 7A1

