

ANNUAL SURVEYS.

6455

No. 130 Survey held at London Date June 13th 1840
 on the Bk Regulus Master Crews
 Tonnage 369 Built at Whitby When built 1812
 By whom built _____ Owners Greenwich
 Port belonging to London Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 1020, 2804, 3873, 4450 & 307, Port of Plymouth July 1839 Classed As with the Steam

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frames <u>Sound & unshaken</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails _____
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, General appearance good, no symptoms of weakness or
 as required by the Instructions, Decay and I am of opinion is fit for the safe conveyance of
dry & perishable cargoes to & from all parts of the world
and may continue as Classed A. 1 with the Steam

Committee Minute 16th June 1840

Character assigned A. 1 Certificate

No. 173 Survey held at London Date June 12th 1840
 on the Bk Jane Lockhart Master W. Choise
 Tonnage 250 Built at Sunderland When built 1820
 By whom built _____ Owners Dunsmuir
 Port belonging to Dominion Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 3666, 3778, 4646, 5779, Port of London 1839 Classed Certified 3 years

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frames <u>Sound & unshaken</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Well found</u>
Plank Shears _____	Wales _____	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging <u>Good</u>
	Windlass _____	Copper _____

General Observations and Opinion, In very good condition & retains her present Class
 as required by the Instructions,

Committee Minute 16th June 1840

Character assigned Class 3A



© 2019

Lloyd's Register Foundation

5900-80507