

# REPORT of SURVEY for REPAIRS.

No. 303 Survey held at London Date July 18 40  
on the Sh. Eliza Ann Master —  
Tonnage 137 Built at New Brunswick When built 1816  
By whom built — Owners J. Rogers  
Port belonging to London Destined Voyage —  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 54 Dated — Classed Fr. 1. S. S. 3 Yr.  
Port Dartmouth, Sta 1249, Lon 3232, 3955, 4523.

## Repairs

At the present time new fore shifts of the planks in the topsides, new ceiling forward two new breast hooks,

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
as required by the Instructions,

This vessel has been reopened above the she lizes in conformity with the Society's Rules and and the timbers of the frame proved in very good condition, as did also the timbers at the bow. No other is fit for the purpose of any use perishable cargo and may

The Amount of Fee.....£ — : 10 : — is received by me

Committee's Minute 7th August 1840

Character assigned Fr. 1. S. S. 3 Yr.

