

ANNUAL SURVEYS.

6664

No. 8 Survey held at London Date August 20th 1840
 on the By Pacific Master Swanson
 Tonnage 175 Built at Wooden When built 1834
 By whom built _____ Owners Barnes & Co
 Port belonging to London Destined Voyage West Indies
 Surveyed Afloat or in Dry Dock Afloat

Survey, No. 3540, 5176 Port of London 1839 Classed GA
5843
 required to state the present Condition of the

Breasthooks	Capstan
Transoms	Pumps
Timbers of the Frame	Masts, Yards, &c.
Topsides	Sails
Wales	Cables
Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Rudder	Standing & Running Rigging
Windlass	Copper

Observations and Opinion, At the present bottom examined, copper fastened & sculked
 required by the Instructions, from the Copper upwards in good condition throughout
and may retain her present class

Committee Minute 14th Septe 1840
 Character assigned GA

No. 459 Survey held at London Date August 28th 1840
 on the Bk John Prie Master Richardson
 Tonnage 279 Built at Sunderland When built 1820
 By whom built _____ Owners Mathews
 Port belonging to London Destined Voyage Trinidad
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 957, 4774 Port of London 1839 Classed Continued 3A
3053, 3590, 5401

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, In very efficient state both in the Hull & stores
 as required by the Instructions, and may continue as Class

Committee Minute 14th Septe 1840
 Character assigned Cont 3A



© 2019
 Lloyd's Register
 Foundation

Lon608-0295