

Change of property  
**REPORT of SURVEY for REPAIRS.**

6720

No. \_\_\_\_\_ Survey held at London Date 18 July 1840  
on the MS Prince George Master \_\_\_\_\_  
Tonnage 482 Built at Swansea When built 1830  
By whom built \_\_\_\_\_ Owners L. Jones  
Port belonging to London Destined Voyage Transport  
If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. \_\_\_\_\_ Dated \_\_\_\_\_ Classed // A /  
Port \_\_\_\_\_

**Repairs**

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Staircase	Wales	Masts, Yards, &c. <u>Sufficient</u>
Staircase Shears	Counter <u>Efficient</u>	Sails <u>Good</u>
Stairways	Plank & Treenails (Outside to the Water's Edge)	Cables
Stairway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,  
as required by the Instructions,

As in good and efficient condition  
and may be continued in her present class

Continued

The Amount of Fee.....£ : : is received by me,

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_