

ANNUAL SURVEYS.

6721

No. 201 Survey held at London Date Sept^r 15th 1840
 on the By Discount Dorne Master A. East
 Tonnage 230 Built at Thorn When built 1825
 By whom built _____ Owners A. Pearson
 Port belonging to Hull Destined Voyage _____
 If Surveyed Afloat or in Dry Dock London

Original Survey, No. 5, 2799, Port of London, Luth 365, 1839 Classed *A, 1
London 4229, 4922, 5299.

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>Good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears <u>"</u>	Wales <u>Good</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, At the present time three new Deck Beams and two pair
as required by the Instructions, of additional Iron hanging knees, and is in an efficient state
for the safe conveyance of dry & perishable cargoes to & from all parts of the World and may continue as before
A, 1 with the Notarish

Committee Minute 18th Sept 1840

Character assigned A, 1 Continue

No. 386 Survey held at London Date Sept^r 15th 1840
 on the Ship Tropic Master J. Phillips
 Tonnage 369 Built at London When built 1819
 By whom built _____ Owners Daniels & Co
 Port belonging to London Destined Voyage Barbados
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 664, 4995, Port of London Classed *A, 1
6040*

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>"</u>
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>Efficient</u>
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, From her general good appearance I am of opinion
as required by the Instructions, she is fit for the safe conveyance of dry & perishable
cargoes to & from all parts of the World and may
retain her present character A, 1 with the Notarish

Committee Minute 18th Sept 1840

Character assigned A, 1 Continue