

ANNUAL SURVEYS.

6726

No. 691 Survey held at London Date Sept 16 1840
 on the B^y Mayflower Master Heasley
 Tonnage 326 Built at Sunderland When built 1834
 By whom built _____ Owners J Coulson
 Port belonging to Scribble Destined Voyage _____
 If Surveyed Afloat or in Dry Dock New frame Dock

Original Survey, No. 117 Port of London 1836 Classed 10A1
Sunderland

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Good *Good* *Can haul* *good different* *1840*

General Observations and Opinion, as required by the Instructions,
At the present time in consequence of being ashore -
5. pl 4. 2nd & 1st Hold beam shifted - Stopped. Caulked
Kulup & ratchet with gelatin on paper as before
In my opinion there is slight to remain off classed 10A1
Fee £ 2

Committee Minute 22nd Sept 1840
 Character assigned 10A1 Record Repair
Damage 5 4 4

©2019
 Lloyd's Register
 Foundation

101608-0371