

# REPORT of SURVEY for REPAIRS. 6852

No. 10 Survey held at London Date Oct 25 1889  
 on the Ship Dale Park Master Shell  
 Tonnage 402 Built at London When built 1828  
 By whom built Lawley & Co Owners Davidson  
 Port belonging to London Destined Voyage Panama  
 If Surveyed Afloat or in Dry Dock Ships Dock

Original Survey, No. \_\_\_\_\_ Dated 1889 Classed 12 A1  
 Port London

Repairs at the present time shipped caulked keel  
to water & coppered on taper -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treennils (Outside to the Water's Edge)	Cables
Hatchway Coverings	Rudder	Anchors No. of
Breasthooks	Copper <u>1889</u>	Standing & Running Rigging

*Good* *Good* *Excellent*  
*Good and*  
*Efficient*


General Observations and Opinion,  
 as required by the Instructions,

*The bottom of this Ship presents a remarkably*  
*good and favorable appearance - and in my*  
*opinion she is eligible to remain as*  
*classified 12 A1*

The Amount of Fee.....£ : : is received by me,

Committee's Minute

Character assigned



© 2019

*George Bayley*

Lloyd's Register  
 Foundation