

REPORT of SURVEY for ^{Coppering} REPAIRS.

No. 156 Survey held at London Date Nov 15th 1839
 on the B. Victory Master West
 Tonnage 236 Built at Liverpool When built 1838
 By whom built Green Owners Hartford Shipp^g
 Port belonging to Hartford Destined Voyage Per Janeiro
 If Surveyed Afloat or in Dry Dock Liverpool Dock

Original Survey, No. 943 Dated 1838 Classed 741
 Port Liverpool

Repairs At the present time consisted to take the
 longitudinal plates & braces replaced with
 metal - Heads of the Iron bolts covered with
 Cement & capped with Lead - Sheathes with
 Yellow Metal on Patent Lark to 10 feet

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions

In my opinion this vessel is eligible to
 her present class 741

The Amount of Fee.....£ : : is received by me,

Committee's Minute 24th Nov 1840

Character assigned 741