

ANNUAL SURVEYS.

6956

No. 746 Survey held at London Date Nov 6th 1840
 on the Ship "Chelmsford" Master White
 Tonnage 299 Built at London When built 1811
 By whom built _____ Owners Chelmsford
 Port belonging to London Destined Voyage _____
 Surveyed ~~At~~ in Dry Dock Imp^l: Curling & Symonds

Original Survey, No. 2038, Port of London

Classed * A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>Not seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. _____
Spirkilling <u>"</u>	Topsoles _____	Sails <u>Good and</u>
Plank Shears <u>"</u>	Wales <u>in a good state</u>	Cables <u>sufficient</u>
Waterways <u>"</u>	Plank and Treennails (Outside to the Water's Edge) <u>Good</u>	Anchors No. of _____
Hatchway Comings <u>"</u>	Rudder _____	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion,
 as required by the Instructions,

At the present time repaired the Copper & felt that
 the Ship is in very good condition and may
 remain as classed

Committee Minute 1st Dec 1840

Character assigned

(Signed) J. Black
1st Dec 1840
Imp^l: Curling & Symonds

No. 396 Survey held at London Date Nov 9th 1840
 on the Barge Ramco Master Pellett
 Tonnage 505 Built at Greenock When built 1830
 By whom built _____ Owners Anderson
 Port belonging to Greenock Destined Voyage Calcutta
 Surveyed ~~At~~ in Dry Dock Imp^l: Newsons

Original Survey, No. 607 Port of Glyke, Ton 580

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings <u>very good</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>very good</u>	Timbers of the Frame <u>very good</u>	Masts, Yards, &c. _____
Spirkilling <u>very good</u>	Topsoles _____	Sails <u>good &</u>
Plank Shears <u>very good</u>	Wales _____	Cables <u>sufficient</u>
Waterways _____	Plank and Treennails (Outside to the Water's Edge) _____	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper <u>Nov 1840</u>

General Observations and Opinion,
 as required by the Instructions,

At the present time Shipped, launched and repaired
 the Bottoms, a very good faithful built Ship in
 excellent condition, and may remain as classed

Committee Minute 1st Dec 1840

Character assigned

(Signed) J. Black
1st Dec 1840
Imp^l: Newsons