

# REPORT of SURVEY for REPAIRS.

No. 34 Survey held at London Date 25 March 1840  
 on the "Achilles" Master Brown  
 Tonnage 252 Built at Princes When built  
 By whom built London Owners London  
 Port belonging to London Destined Voyage to London  
 If Surveyed Afloat or in Dry Dock Under the Mast

Original Survey, No. 234, 2094, Dated 30.10.38, 1811,  
 Port London Classed A-1

## Repairs

Shipped overboarded & washed  
with yellow metal at the present time.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Toprides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treennails (Outside to the Water's edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Yellow Metal</u>	Standing & Running Rigging

General Observations and Opinion,  
 as required by the Instructions,

Is in Substantial & sufficient condition  
fit for conveyance of ore and for the cargo as  
to and from all parts of the world may be  
continued as classed

The Amount of Fee.....£ : : is received by me,

Committee's Minute 1st Dec 1840

Character assigned Fit for service