Coppering

REPORT of SURVEY for REPAIRS.

No. 642 Survey held at London Date Jan.y 22 1840

on the Ship Ann Lockerby Master Thomas Bird

Tonnage 365 Built at Liverpool When built 1834

By whom built Thomas Wilson Owners Lockerby

Port belonging to Liverpool Destined Voyage Calcutta

If Surveyed Afloat or in Dry Dock Mess.rs Fowlers Dock

Original Survey, No. 263 Dated 1834 Classed 12 A 1

Port Liverpool

Repairs at the present time cut this from the keel and coppered to the trade

The Surveyor is also required to state the present Condition of the

Decks		Transoms		Windlass	
Upper Deck Beams & Fastenings		Timbers of the Frame		Capstan	
Lower Deck Beams & Fastenings		Topsides		Pumps	
Spirketting	Good	Wales	Good	Masts, Yards, &c.	Good & efficient
Plank Shears		Counter		Sails 3 Sets	
Waterways		Plank and Treenails (Outside to the Water's Edge)		Cables 2	
Hatchway Comings		Rudder		Anchors No. of 3. 1. 1	
Breasthooks		Copper 1840		Standing & Running Rigging	

General Observations and Opinion, as required by the Instructions, This Ship has a fine and good appearance and appears fully eligible to her present class 12 A 1

George Bayley

The Amount of Fee.....£ : : is received by me.

Committee's Minute 1st Mar 1840

Character assigned 12 A 1 retain copper

G. F. SEYFANG, PRINTER, FARRINGDON STREET, LONDON.

© 2019 Lloyd's Register Foundation

LON 609-0139