

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 105 Survey held at London Date Jan^y 16 1848
 on the By Bianonia Master
 Tonnage 106 Built at Yarmouth When built 1827
 By whom built _____ Owners Mathews x
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Franca's Dock Wagon

London 132 &
 Original Survey, No. 2266, Dated 1838 Classed Seaman's A 1 from 1825
 Port of Liverpool, London 6127.

Repairs At the present time Bottom examined & caulked from the Upper to the Garboard

The Surveyor is also required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Windlass _____
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>Stand</u>	Capstan _____
Lower Deck Beams & Fastenings <u>"</u>	Topsides <u>Good</u>	Pumps _____
Spirkettling _____	Wales _____	Masts, Yards, &c. <u>Good</u>
Plank Shears _____	Counter _____	Sails _____
Waterways <u>Good</u>	Plank & Treennails (Outside in the Water's Edge) <u>"</u>	Cables <u>Sufficient</u>
Hatchway Coverings _____	Rudder _____	Anchors No. of _____
Breasthooks _____	Copper _____	Standing & Running Rigging _____

General Observations and Opinion, Form of opinion was good condition to retain her present shape
 as required by the Instructions,



© 2019

The Amount of Fee.....£ _____ is received by me,

Committee's Minute 1st Dec 1848

Character assigned C.P.B.A

Lloyd's Register Foundation