

REPORT of SURVEY for REPAIRS.

69/14

Coppering

No. 165 Survey held at London Date June 9 18 40
 on the Brig Ellen Master Chadwick
 Tonnage 300 Built at Peth When built 1836
 By whom built _____ Owners Woolbold
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Mountain Dock

Original Survey, No. 243, Dated _____ 1835 Classed SA-1
 Port London

Repairs

*At the present time Shepper carried from
 keel to water & resheathed on Paper & hemp sheathing
 with yellow electal to 10 ft buches*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennils (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

Good *Good* *Good & efficient*

General Observations and Opinion,
 as required by the Instructions,

*In my opinion this vessel is eligible to remain
 as classed SA-1*

The Amount of Fee.....£ : : is received by me

Committee's Minute get Print 18 40

Character assigned SA-1