

No. 6999

Survey held at

London Repairs

Date

Sept 251837

on the

Brig Britton Castle

Master

Canny

Tonnage

270

Built at

SwitzerlandWhen built 1833

By whom built

Owners

Baker & Co

Port belonging to

London

Destined Voyage

Jamaica

If Surveyed Afloat or in Dry Dock

Cuttle Dock

Original Survey, No.

Port of

London1835 Classed YA1

The Surveyor is required to state the present Condition of the

Decks

Good

Breasthooks

Good

Capstan

Upper Deck Beams & Fastenings

✓

Transoms

✓

Pumps

Good

Lower Deck Beams & Fastenings

✓

Timbers of the Frame

✓

Masts, Yards, &c.

✓

Spirketting

✓

Topsides

✓

Sails

Rebunking

Plank Shears

✓

Wales

✓

Cables

Sufficient

Waterways

✓

Plank & Treennails

✓Anchors No. of 364 181 R

Hatchway Comings

✓

Rudder

✓

Standing & Running Rigging

Rebunking

Windlass

✓Coppered on Sept 1837 to 1838General Observations and Opinion,
as required by the Instructions,

At the present time caulking from keel to bales
about 300 Treennails shifted and generally rebunked
is in good condition and in my opinion should remain
Classed YA1

George Bayley

Committee Minute

183

Character assigned