

ANNUAL SURVEYS.

7050

No. 117 Survey held at London Date Dec 1st 1840
 on the Brig "Sis" Master Fisher
 Tonnage 248 Built at Jersey When built 1838
 By whom built _____ Owners Fisher
 Port belonging to Basil Destined Voyage Barbadoes
 Surveyed Dec 1 in Dry Dock Messrs. Coulson & Young

Original Survey, No. 113 Port of Jersey, London 9/11

Classed S.A.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Cupstn
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Sheers	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Riggng
	Windlass	Copper

At the present time, Shipper of the Old Briton. Condition the bottom. I thought with yellow paint on paper, the Brig is in very poor condition

General Observations and Opinion,
 as required by the Instructions,

Committee Minute

Character assigned

No. 922 Survey held at London Date Dec 9th 1840
 on the Ship "Asia" Master Freeman
 Tonnage 523 Built at Calcutta When built 1815
 By whom built _____ Owners Clapham
 Port belonging to _____ Destined Voyage _____
 Surveyed Dec 1 in Dry Dock Messrs. Coulson & Young

Original Survey, No. 112, 342b Port of London

Classed *A.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Cupstn
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Sheers	Wales	Cables
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Riggng
	Windlass	Copper

At the present time Shipper. Of the old Copper Condition the Bottom and Re. Clapham. on paper a strong Ship a very different state and not given as Clapham

General Observations and Opinion,
 as required by the Instructions,

Committee Minute

Character assigned