

ANNUAL SURVEYS.

7062

No. Survey held at LONDON Date Dec 3rd 1840
 on the St. Catherine Master
 Tonnage 186 Built at Yarmouth When built 1837
 By whom built Owners St. Hubert
 Port belonging to LONDON Destined Voyage Barbadoes
 If Surveyed Afloat or in Dry Dock At St. Hubert

Original Survey, No. Part of LONDON Feb 11th Classed 3.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Top-sides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennils (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Upper deck somewhat good in many places
 as required by the Instructions, the ship is to remain as afloat at

Committee Minute 1840

Character assigned

No. 305 Survey held at LONDON Date Dec 4 1840
 on the St. Maria Master McKellan
 Tonnage 313 Built at Glasgow When built 1819
 By whom built Owners Barclay
 Port belonging to Glasgow Destined Voyage Lydney
 If Surveyed Afloat or in Dry Dock At St. Maria

Original Survey, No. 189, 471 Part of Glasgow Classed 3.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Top-sides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennils (Outside to the Water's Edge.)	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Upper deck & hull in good order. Little, but no repairs
 as required by the Instructions, needed & thoroughly overhauled. In many places

Committee Minute 1840

Character assigned

Lloyd's Register
 Foundation