

REPORT of SURVEY for REPAIRS.

Channel of Barnes 7071

No. 87 Survey held at London Date 14 Dec 1840
 on the By James Gibson Master Robert
 Tonnage 204 Built at Belfast When built 1839
 By whom built _____ Owners Clay & Co
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock floor

Original Survey, No. 273 Dated _____ Classed 10 A1

Port Belfast London 6109 & 6936

REPAIRS

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capestan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkelting	Wales	Masts, Yards, &c.
Plank Sheers <u>good</u>	Counter <u>good</u>	Sails
Waterways	Plank and Treennails (Outside of the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, Is in good and efficient condition and may remain as classed.

The Amount of Fee.....£ 1 is received by me. Montenay
 Committee's Minute 22 Dec 7 1840
 Character assigned 10 A1

Clay & Gibson

LON 609-0259