

REPORT of SURVEY for REPAIRS.

No. 246 Survey held at London Date 4th Dec 1837
 on the Ship Maria Master Miles
 Tonnage 280 Built at Lamberton When built 1833
 By whom built _____ Owners W. H. Miles
 Port belonging to Bothway Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Ritchie's Dock

Original Survey, No. 1517, Dated _____, 1836 Classed S.A.1
 Port Liverpool Glyde Glas

Repairs at the present time carried from the keel to water
upper course wood sheathed - & coppered and paper to
13ft bins -

This ship presents throughout a very favorable
appearance -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treeneils (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, In my opinion this vessel entitled to retain
as required by the Instructions, in present class S.A.1

The Amount of Fee £ _____ is received by me

Committee Minute 10th Jan 18³⁸

Character assigned S.A.1 George Bayley
See London Glyde Glas