

ANNUAL SURVEYS.

No. 505 Survey held at London Date Feb. 2 1841
 on the Am City of Hamburgh Master Thomas
 Tonnage 279 Built at London When built 1814
 By whom built _____ Owners Gen. Sir Navigation Co
 Port belonging to London Destined Voyage Hamburgh
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. 1515, 3550 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

| | | |
|--|---|------------------------------------|
| Decks <u>good</u> | Breasthooks <u>good</u> | Capstan _____ |
| Upper Deck Beams & Fastenings <u>"</u> | Transoms <u>good when seen</u> | Pumps _____ |
| Lower Deck Beams & Fastenings <u>"</u> | Timbers of the Frame <u>"</u> | Masts, Yards, &c. _____ |
| Spirkettling <u>"</u> | Top-sides _____ | Sails <u>good & sufficient</u> |
| Plank Shears <u>"</u> | Wales _____ | Cables _____ |
| Waterways <u>"</u> | Plank and Treennails <u>very good</u> (Outside to the Water's Edge.) | Anchors No. of _____ |
| Hatchway Comings <u>"</u> | Rudder _____ | Standing & Running Rigging _____ |
| | Windlass _____ | Copper <u>new</u> |

General Observations and Opinion,
 as required by the Instructions,

*At the present time, Shipper's Certificate and
 Referred to the bottom in paper -
 The vessel is in very good condition and may
 remain as shipped*

Committee Minute 12th Feb 1841

Character assigned 12 A 1 *See* Copy

Duplicate
 No. _____ Survey held at London Date Feb. 2nd 1841
 on the Ship Helara Master Slane
 Tonnage 778 Built at Calcutta When built 1815
 By whom built _____ Owners Slane
 Port belonging to London Destined Voyage Barbadoes
 If Surveyed ~~Afloat~~ in Dry Dock Mr. Pitchers

Original Survey, No. _____ Port of _____ Classed * A. 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------------|--|------------------------------------|
| Decks _____ | Breasthooks _____ | Capstan _____ |
| Upper Deck Beams & Fastenings _____ | Transoms <u>Good when seen</u> | Pumps _____ |
| Lower Deck Beams & Fastenings _____ | Timbers of the Frame _____ | Masts, Yards, &c. _____ |
| Spirkettling <u>Good</u> | Top-sides _____ | Sails <u>Good & sufficient</u> |
| Plank Shears _____ | Wales _____ | Cables _____ |
| Waterways _____ | Plank and Treennails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of _____ |
| Hatchway Comings _____ | Rudder _____ | Standing & Running Rigging _____ |
| | Windlass _____ | Copper <u>new</u> |

General Observations and Opinion,
 as required by the Instructions,

*The Ship is in very good Condition, and may
 remain as shipped*

Committee Minute _____ 1841

Character assigned _____