

ANNUAL SURVEYS.

No. 115 Survey held at London Date July 16th 1841
 on the Ship Neptune Master Miles
 Tonnage 267 Built at Switzerland When built 1830
 By whom built _____ Owners Fenwick
 Port belonging to London Destined Voyage Habibes
 If Surveyed Afloat or in Dry Dock At the Owners Dock

Original Survey, No. 1213 Port of London Classed GA1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Notes: Upper Deck Beams & Fastenings, Spirketting, Plank Shears, Waterways, Hatchway Comings, and Windlass are marked 'Good'. Transoms, Timbers of the Frame, and Treenails are marked 'Fair'. Masts, Yards, &c., Sails, Cables, Anchors, and Rigging are marked 'Sufficient'.

General Observations and Opinion: Is throughout in a very efficient state to continue as required by the Instructions, in her present shape.

Committee Minute 19th Febry 1841

Character assigned GA1

No. 275 Survey held at London Date Feb 17th 1841
 on the Ship Emily Master J. S. Brooke
 Tonnage 100 Built at Switzerland When built 1832
 By whom built _____ Owners Armedale
 Port belonging to London Destined Voyage Hambro
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 5105 Port of London Classed V.1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

Notes: Upper Deck Beams & Fastenings, Spirketting, Plank Shears, Waterways, Hatchway Comings, and Windlass are marked 'Good'. Transoms, Timbers of the Frame, and Treenails are marked 'Fair'. Masts, Yards, &c., Sails, Cables, Anchors, and Rigging are marked 'Sufficient'.

General Observations and Opinion: Every part in all her fastenings in appearance & decay as required by the Instructions, and all in good condition to continue her present shape with the necessary

Committee Minute 10th Febry 1841

Character assigned V.1