

ANNUAL SURVEYS.

7360

No. 12 Survey held at London Date March 20th 1841
 on the Bk Kyle Master Fletcher
 Tonnage 333 Built at Dunbarton When built 1837
 By whom built _____ Owners Brown & Co
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 1032, Port of Plyde 1039 Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time Bottom stripped, caulked
 as required by the Instructions, and sheathed with yellow metal,
Is in good condition to continue in her present class

Committee Minute 26th March 1841

Character assigned 10 A 1 Good

No. 119 Survey held at London Date March 20th 1841
 on the Bk Orion Master C Almond
 Tonnage 200 Built at Scarbis When built 1834
 By whom built Tindall Owners Tindall & Co
 Port belonging to Scarbis Destined Voyage Dublin
 If Surveyed Afloat or in Dry Dock London

Original Survey, No. *39 Port of Scarbis 1839 Classed 6 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, Caulked in 1840 and is in a very efficient state
 as required by the Instructions, to retain her present class

Committee Minute 26th March 1841

Character assigned 6 A 1 Good