

ANNUAL SURVEYS.

7418

No. 108 Survey held at London Date 3^d April 1841
 on the "Eddy Stone" Master Marshall
 Tonnage 214 Built at Nullo When built 1802
 By whom built — Owners Benson
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Atchiffe crop bags

Original Survey, No. 1 Port of Stockton Classed A.1

The Surveyor is required to state the present Condition of the

Decks fair drawn off iron Breasthooks many in fair condition Capstan Survey annexed
 Upper Deck Beams & Fastenings firm Transoms good & sound Pumps —
 Lower Deck Beams & Fastenings do Timbers of the Frame blue seen old Masts, Yards, &c. apparently good
 Spirketting part not good Topsides good Sails not seen
 Plank Shears part not in good state Wales good Cables the good the other too small
 Waterways good Plank and Treenails — Anchors No. of sufficient
 Hatchway Comings good Rudder good Standing & Running Rigging good
 Windlass good Copper wood sheathing good

General Observations and Opinion, There is a large clamp wrought under the Hold Beams
as required by the Instructions, that affords considerable strength, the wales, black-
shakes, topsides, and sheer shakes, and the greater part of the Plank
sheers are in a very good condition, also the keelsons, lying in the
floor & side shakes. The other parts of the hulling is old & worn & part
of the upper deck clamps not good the
ends of some of the beams are decayed
and the apron is rotten
 Committee Minute 10th April 1841
 Character assigned Reduced to F.1
16th April
27th April
10th May
16th May
16th May

No. 183 Survey held at London Date 2 April 1841
 on the "Resolution" Master Carter
 Tonnage 393 Built at Yarmouth When built 1805
 By whom built — Owners Carter & Harby
 Port belonging to London Destined Voyage Zuebee
 If Surveyed Afloat or in Dry Dock Afloat & Dry Dock

Original Survey, No. 1438, 2393 Port of London Classed A.1

The Surveyor is required to state the present Condition of the

Decks in fair condition Breasthooks good Capstan —
 Upper Deck Beams & Fastenings good Transoms do Pumps —
 Lower Deck Beams & Fastenings firm Timbers of the Frame do Masts, Yards, &c. new fore mast
 Spirketting — Topsides do Sails 2 sets
 Plank Shears good Wales do Cables 2 C good & sufficient
 Waterways — Plank and Treenails — Anchors No. of sufficient
 Hatchway Comings — Rudder good Standing & Running Rigging good
 Windlass do Copper wood sheathing good

General Observations and Opinion, Mostly new false keel, & ripe upaired sheathing
unailed and caulked, from the keel to the upper part of the
wales new iron wale put in & other knees additionally bolted
 Committee Minute 10th April 1841
 Character assigned R.1
16th April
27th April
10th May
16th May
16th May

Law of opinion &c. may remain
 as Clapped
 Lloyd's Register
 Foundation