

ANNUAL SURVEYS.

7512

No. 463 Survey held at London Date May 4 1841
 on the Bk Louisa Master Pullo
 Tonnage 306 Built at Calcutta When built 1824
 By whom built _____ Owners Smith & Co
 Port belonging to Calcutta Destined Voyage _____
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 5990* Port of London Feb'y 1840 Classed A, 1 Asterisk

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|--|
| Decks | Breasthooks <u>Sound</u> | Capstan <u>Good</u> |
| Upper Deck Beams & Fastenings | Transoms <u>"</u> | Pumps <u>"</u> |
| Lower Deck Beams & Fastenings | Timbers of the Frame <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Spirketting <u>Good</u> | Topsides <u>"</u> | Sails <u>"</u> |
| Plank Shears <u>"</u> | Wales <u>"</u> | Cables <u>Well found</u> |
| Waterways <u>Firm</u> | Plank and Treenails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of <u>"</u> |
| Hatchway Comings | Rudder <u>"</u> | Standing & Running Rigging <u>Good</u> |
| | Windlass <u>"</u> | Copper <u>"</u> |

General Observations and Opinion, Very firm at her fastenings & from her general good
 as required by the Instructions, appearance I am of opinion is fit for the safe conveyance
of dry & perishable cargoes to & from all parts of the World
and may continue A, 1 with the Asterisk

Committee Minute 7th May 1841 Pauline from the Copper over all

Character assigned A, 1 Asterisk

No. 204 Survey held at London Date May 4 1841
 on the Ss Sarah Master Watford
 Tonnage 132 Built at Sunderland When built 1837
 By whom built _____ Owners Watford & Co
 Port belonging to Witcham Destined Voyage Memel
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 397 Port of Liverpool 1839 Classed 5 A 1
Dundee, Sunderland 691, Liv. 2815

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|-------------------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirketting <u>Good</u> | Topsides <u>"</u> | Sails <u>Good</u> |
| Plank Shears <u>"</u> | Wales <u>"</u> | Cables <u>"</u> |
| Waterways | Plank and Treenails <u>Good</u> (Outside to the Water's Edge.) | Anchors No. of <u>Sufficient</u> |
| Hatchway Comings | Rudder <u>"</u> | Standing & Running Rigging <u>"</u> |
| | Windlass <u>"</u> | Copper <u>"</u> |

General Observations and Opinion, Is in a very efficient state to retain her
 as required by the Instructions, present class

Committee Minute 7th May 1841

Character assigned 5 A 1



© 2019

Lloyd's Register
Foundation