

ANNUAL SURVEYS.

7551

No. _____ Survey held at London Date May 5th 1841
 on the Ship Arab Master _____
 Tonnage 415 Built at Stockton When built 1840
 By whom built _____ Owners Swire
 Port belonging to London Destined Voyage New Zealand
 Surveyed ~~Afloat~~ in Dry Dock Ship: Curling & Youngs

Original Survey, No. _____ Port of _____ Classed SA

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, { At the present time. Caretied the Bottom and
Coppered to the wales, a good Ship of her class
in my opinion should remain as classed

Committee Minute _____ 184

Character assigned _____

Wm. J. Clark

No. 1353 Survey held at London Date May 6th 1841
 on the Ship Bucephalus Master Fletcher
 Tonnage 439 Built at Newcastle When built 1840
 By whom built _____ Owners Smith &c.
 Port belonging to London Destined Voyage Calcutta
 Surveyed ~~Afloat~~ in Dry Dock Ship: Fletcher dock

Original Survey, No. 1353 Port of Newcastle Classed 12 A

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,
 as required by the Instructions, { A very excellent & well built Ship, in an
efficient state & may remain as classed

Committee Minute 21st May 1841

Character assigned 12 A

Wm. J. Clark



© 2019

Lloyd's Register
Foundation