

# ANNUAL SURVEYS.

No. 100 Survey held at Sunder Date June 2<sup>nd</sup> 1841  
 on the Mary Roberts Master J. Perry  
 Tonnage 25 Built at Milford When built 1836  
 By whom built \_\_\_\_\_ Owners Perry & Co  
 Port belonging to Milford Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3082, 6230 Port of Sunder

Classed 10 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, In good condition both in the Hull & Stores, and  
 as required by the Instructions, eligible to retain her present Class

Committee Minute 8th June 1841

Character assigned 10 A 1

No. 102 Survey held at Sunder Date June 2<sup>nd</sup> 1841  
 on the By Harmony Master W. Taylor  
 Tonnage 231 Built at Yarmouth When built 1837  
 By whom built \_\_\_\_\_ Owners Le Sueur  
 Port belonging to Sunder Destined Voyage Sabador  
 If Surveyed Afloat or in Dry Dock on the Mags

Original Survey, No. 1141, 2430 Port of Sunder

Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge.)	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, Upperworks caulked and a general overhaul in the  
 as required by the Instructions, Hull & rigging and in good condition to retain  
her present Class

Committee Minute 8th June 1841

Character assigned 11 A 1



© 2019

Lloyd's Register  
Foundation