

REPORT of SURVEY for REPAIRS.

Survey held at London Date May 29th 1841
 Barque "Sida" Master Harry Kasmare
 Age 159 Built at London When built 1801
 by whom built _____ Owners Smith &c.
 belonging to London Destined Voyage _____
 surveyed ~~At~~ in Dry Dock M. King

Original Survey, No. 2891, 3282, Dated _____ Classed A.1
London 4192, 4574, 4853, 6302, 6325,

REPAIRS

At the present time, stripped off the Copper
 and out listings in the wood sheathing. Caulked
 the Seal seam wood ends, and the Strake
 under the wales. Shifted the upper & Lower
 Counter and 4 Stem timbers.

Present Condition of the

Decks	Transoms <u>Wm Hanson expended</u>	Windlass <u>Good</u>
Upper Deck Beams & Fastenings	Timbers of the Frame <u>not men</u>	Capstan <u>"</u>
Lower Deck Beams & Fastenings	Topsides <u>"</u>	Pumps <u>"</u>
Spirketting	Wales <u>"</u>	Masts, Yards, &c. <u>"</u>
Plank Shears	Counter <u>Good</u>	Sails <u>"</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <u>"</u>
Hatchway Comings	Rudder <u>Good</u>	Anchors No. of <u>"</u>
Breasthooks	Copper <u>new 1841</u>	Standing & Running Rigging <u>"</u>

General Observations and Opinion,

This Ship is in a good state. fit for the
 conveyance of dry Cargoes, and in my Opinion
 may remain as classed

The Amount of Fee.....£ 2: — : — is received by me,

Committee's Minute 15th June 1841

Character assigned A.1



© 2019

Lloyd's Register
 Foundation

LON 610 - 0355