

# ANNUAL SURVEYS.

7703

No. 84 Survey held at London Date July 7<sup>th</sup> 1841  
 on the By Naylor Master H. J. J. J.  
 Tonnage 149 Built at Hull When built 1815  
 By whom built \_\_\_\_\_ Owners Handwriting  
 Port belonging to George Destined Voyage Hamburg  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 5808, 6310, Port of London 1840 Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks <u>Sound</u>	Capstan _____
Upper Deck Beams & Fastenings <u>Good &amp; Firm</u>	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>Sound &amp; even</u>	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Good</u>
Plank Shears <u>"</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>Sufficient</u>
Hatchway Comings <u>"</u>	Rudder <u>"</u>	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper _____

General Observations and Opinion, Is in an efficient state for the safe conveyance  
 as required by the Instructions, of any perishable cargo & may continue as before

Committee Minute 16th July 1841

Character assigned A, 1

No. 288 Survey held at London Date July 7<sup>th</sup> 1841  
 on the By Libra Master Gibbons  
 Tonnage 100 Built at Dunee When built 1832  
 By whom built \_\_\_\_\_ Owners Gibbons & Co  
 Port belonging to London Destined Voyage Open to  
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 2056, Port of London 1839 Classed Continued A, 2 years

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirkettling <u>Good</u>	Topsides _____	Sails <u>With</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>found</u>
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, Her general appearance very fair & is in good  
 as required by the Instructions, condition to retain her present class

Committee Minute 16th July 1841

Character assigned Class 2 A



© 2019

Lloyd's Register  
Foundation

LON 610-0436