

# REPORT of SURVEY for REPAIRS.

No. 182 Survey held at London Date July 26<sup>th</sup> 1841  
 on the St. Martin Master Hall  
 Tonnage 207 Built at New Brunswick When built 1826  
 By whom built - Owners Criswell  
 Port belonging to London Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock Dry Dock

Original Survey, No. 318, dated 1222 Pated 1961, 2288, Classed A. 1. 55. 58. 59.  
 Port Liverpool, Lon. 4408, 5995.

## REPAIRS

*Shipped new gripe & lower piece  $\frac{5}{8}$  stem Hold beams and fastened  
 and sheathed with yellow metal upperworks & waterways  
 caulked*

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Copstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <i>Sufficient</i>
Plank Shears	Counter <i>good</i>	Sails <i>in quarters</i>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Cables <i>in good condition</i>
Hatchway Comings	Rudder	Anchor's No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *Appears sound & sufficient for the service and  
 of any and perishable cargo and may be returned as  
 clapped*

The Amount of Fee.....£..... is received by me,

Committee's Minute *6th August 1841*

Character assigned *Fit*

© 2019

Lloyd's Register  
 Foundation